



NOTES

- 1) REMOVE ALL LEAD AND OTHER FLASHING BEFORE INSTALLING FIELD-FABRICATED PIPE SEAL
- 2) FLASHING WRAPPED AROUND PIPE SHALL HAVE 3" (8 cm) MINIMUM MEMBRANE SPLICE.
- 3) TEMPERATURE MUST NOT EXCEED 180° F (82° C)

500-8B

FIELD FABRICATED
NEW HOT STACK

CARLISLE

© 2011 CARLISLE CORPORATION